

Jitendra Marathe  
A.M.I.E (India)  
Chartered Engineer

MERIDIAN CONSULTANTS  
17, Shree Vishnu Complex, Opp. P.L.  
Deshpande Garden, Sinhgad Road,  
Pune -411030 email- [mecspune@gmail.com](mailto:mecspune@gmail.com)  
Cell No. : 9422318467, Telefax : 020-24252017

**STRUCTURAL STABILITY CERTIFICATE OF BUILDING**

Ref.No. - MECS/09/2023/01

Date - 31<sup>st</sup> May 2023

To,  
Principal,  
GG International School,  
74, Swar Ganga, 177, Vallabh Nagar,  
Pimpri Colony, Pune,  
Maharashtra - 411018

Sub: Checking Structural Stability of GG International School Building situated at 74,  
Swar Ganga, 177, Vallabh Nagar, Pimpri Colony, Pune- 411018.

Ref: As per the condition survey of school building conducted by us on the date of  
27<sup>th</sup> May 2023.

I hereby certify that I had inspected the above referred building with a view to  
ascertain the Structural Stability of the building. The structural elements  
inspected included foundations, Plinth, Columns, Beams and Slabs at each floor.  
The observations have been recorded as per the Structural Audit/ Condition Survey  
format enclosed herewith.


I have also gone through the Architectural and Structural drawings available for  
the existing building & checked whether there is no change in the use of any  
Room or Part of the Building. Nothing objectionable was observed.

I therefore certify that the said building structural work is safe and stable for  
the building user as mentioned in this Stability format.

Thanking You.



Jitendra Marathe,  
Meridian Consultants, Pune  
PMC License No- 269



Principal  
GG International School  
Pimpri, Pune-18.  
CBSE Affiliation No.1130198

For G. G. International School



Authorised Signatory

**Jitendra Marathe**  
A.M.I.E (India)  
Chartered Engineer

**MERIDIAN CONSULTANTS**  
17, Shree Vishnu Complex, Opp. P.L.  
Deshpande Garden, Sinhgad Road,  
Pune -411030 email- [mecspune@gmail.com](mailto:mecspune@gmail.com)  
Cell No. : 9422318467, Telefax : 020-24252017

**STRUCTURAL AUDIT/CONDITION SURVEY REPORT**

**Name of the Building:** GG International School  
**Description:** G+5 Floor RCC Framed Building  
**Address-** 74, Swar Ganga, 177, Vallabh Nagar, Pimpri Colony,  
Pune, Maharashtra - 411018  
**Society Name:** Kamala Education Society  
**Age of the Building:** 16 Years  
**Contact Person:-** Mrs. Deepali Sawant **Tel. No:** 9021938775  
**Inspection Report Date:** 30/05/2023 **INSPECTED BY:** Jitendra Marathe.

**OBSERVATIONS**

S. NO.	DESCRIPTION	REMARKS
1.	Foundation Strata	Could not observe.
	Visual Inspection	Ground Strata seems to be ok.
	Settlement Of Columns	No.
	Settlement Of Walls	No.
	Cracks In Col., Walls, Joint At Plinth	No.



*Madhavi*  
Principal  
GG International School  
Pimpri, Pune-18.  
CGSE Affiliation No. 1130198

For G. G. International School

*Jitendra Marathe*  
Authorized Signatory

S. NO.	DESCRIPTION	REMARKS
2.	Super Structure Inspection	No signs of any settlement and cracks are observed.
	Cracks In Columns/ Rusting Of Steel / Exposed Steel	No.
	Cracks In Beams /Rusting Of Steel / Exposed Steel	No.
	Cracks In Slabs / Rusting Of Steel / Exposed Steel	No. Toilet areas are covered with false Ceilings hence could not be inspected.
	Cracks In External Walls	No.
	Cracks In Internal Walls	No
3.	Leakages & Dampness In External Walls	No.
4.	Toilet Leakages, Cracks,	No.
5.	Terrace Water Proofing Inspection	Waterproofing in good condition.
6.	Leakage & Dampness On The Top Floor Slab	No.
7.	Inspection Of Water tank Above Terrace	Couldn't be accessed
8.	Inspection Of Underground Water Tank	No.
9.	Leakages & Damages: - Plumbing Lines/Waterlines, Drainage Lines For G. G. International School	Not seen.



*Shagroni*  
Principal

GG International School  
Pimpri, Pune-18.  
CBSE Affiliation No. 1130198

*[Signature]*  
Authorized Signatory

**Jitendra Marathe**  
A.M.I.E (India)  
Chartered Engineer

**MERIDIAN CONSULTANTS**  
17, Shree Vishnu Complex, Opp. P.L.  
Deshpande Garden, Sinhgad Road,  
Pune -411030 email- [mecspune@gmail.com](mailto:mecspune@gmail.com)  
Cell No. : 9422318467, Telefax : 020-24252017

S. NO.	DESCRIPTION	REMARKS
10.	Electrical Line	-----
11.	Building Last Repaired Details	No Structural Repairing Has Done
	Date	--
	Cost Of Repair Work	--
	What was repaired?	--
12.	Date Of Construction Of Building	Not Available
13.	R.C.C. / Load Bearing Structure	RCC Framed Structure
14.	Idea About Foundation Strata From Surrounding Areas & Enquiry	Not Applicable.
15.	High Flood Level	Not Relevant.
	HFL During This Monsoon	Not Relevant.
	HFL During Last Five Years	Not Relevant.
16.	Any Cracks Observed During Earthquake	No Record Available.
17.	Architectural Plans Available	Yes.
18.	Structural Plans Available For G. G. International School	Yes.



*[Signature]*  
Authorised Signatory



Principal  
GG International School  
18.  
120198  
G.G. International School  
CBSE Affiliation

**Jitendra Marathe**  
A.M.I.E (India)  
Chartered Engineer

**MERIDIAN CONSULTANTS**  
17, Shree Vishnu Complex, Opp. P.L.  
Deshpande Garden, Sinhgad Road,  
Pune -411030 email- [mecspune@gmail.com](mailto:mecspune@gmail.com)  
Cell No. : 9422318467, Telefax : 020-24252017

19.	Building Completion Certificate Date	Certificate No. 146/2010, dated 06/09/2010
20.	Building Is Designed For Earthquake Code -1893-1984	Yes.
	Building Is Designed For Earthquake Code -1893- 2002	Yes.
21.	Tests Recommended	No
	Rebound Hammer Test	--
	Concrete Core Cutting & Compression Testing	--
	Half Cell Potential Test For Determining The Probability Of Corrosion In Embedded Steel	--
	Carbonation Test For Carbonation depth Measurement For Steel	--
	Ultrasonic Pulse Velocity Test (UPV) For Strength Assessment Of Concrete	--
	Integrity Test For Pile Foundations	--



*Pragya*



Principal  
G.G. International School  
Pimpri - 411018.  
CGIS CBSE Affiliated

For G. G. International School

*[Signature]*  
Authorised Signatory

Jitendra Marathe  
A.M.I.E (India)  
Chartered Engineer

MERIDIAN CONSULTANTS  
17, Shree Vishnu Complex, Opp. P.L.  
Deshpande Garden, Sinhgad Road,  
Pune -411030  
E. Mail : mecpune@gmail.com  
Cell No. : 9422318467, Telefax : 020-24252017

S. NO.	DESCRIPTION	REMARKS
22.	<u>REPAIRS / RETROFIT SUGGESTED</u> 1) Some cracks in Plaster on internal & external walls on all floors & the same shall be repaired 2)	
23.	<u>CONCLUSION</u> No structural modifications are done in the building Subject Building is safe, sound and stable to carry out desired loads and hence the structure is fit for its performance to the intended use.	

Regards,

Jitendra Marathe

Meridian Consultants, Pune

Structural Engineer

PMC License No- 269



Principal  
GG International School  
Pimpri, Pune-18.  
CBSE Affiliation No. 1130198

For G. G. International School

Authorised Signatory